



3 year guarantee

ASAP'SORBER 20

CE 0082 EN 355

(EN) Lanyard with energy absorber for ASAP and ASAP LOCK

(FR) Longe avec absorbeur d'énergie pour ASAP et ASAP LOCK

75 g

WARNING


Activities involving the use of this equipment are inherently dangerous. You are responsible for your own actions and decisions.

- Before using this equipment, you must:
 - Read and understand all Instructions for Use.
 - Get specific training in its proper use.
- Become acquainted with its capabilities and limitations.
- Understand and accept the risks involved.



FAILURE TO HEED ANY OF THESE WARNINGS MAY RESULT IN SEVERE INJURY OR DEATH.

Traceability and markings / Traçabilité et marquage



CE 0082

- a. Body controlling the manufacture of this PPE
b. Notified body that carried out the CE type inspection
- Apave Sudeurope SAS
8 rue Jean-Jacques Vornazza
Z.A.C. Saumay-Séon - CS 60193
13322 MARSEILLE CEDEX CEDEX 16
N°0082

- c. Traceability: datamatrix = product reference + individual number

e. Individual number

00 000 AA 0000

- f. Year of manufacture
g. Day of manufacture
h. Control or name of inspector
i. Incrementation

j. Standards

k. Carefully read the instructions for use

l. Model identification

PETZL
ZI Cidex 105A
38920 Crolles
France


PETZL.COM

ISO 9001
© Petzl

Made in France

1. Field of application (text part) Champ d'application (partie texte)

2. Nomenclature



3. Inspection, points to verify Contrôle, points à vérifier



PPE checking
Vérification EPI

PETZL.COM




4. Compatibility Compatibilité



ASAP
ASAP LOCK


6. Installation



7. Precautions for use Précautions d'utilisation



Clearance Tirant d'air



8. Additional information

Informations complémentaires

A. Lifetime / Durée de vie

Serial n°
XXXX XX XXXX + 10 years
ans

B. Markings Marquage



C. Acceptable T° T° tolérées

+ 80°C / + 176°F
- 40°C / - 40°F

D. Precautions for use / Précautions d'usage



E. Cleaning - Disinfection / Nettoyage - Désinfection



F. Drying / Séchage

+ 30°C maxi.
+ 86°F maxi.



G. Storage - Transport Stockage - transport

+ 30°C / + 86°F
+ 10°C / + 60°F



H. Modifications - Repairs Modifications - Réparations



I. FAQ - Contact Questions - Contact



